

[별첨1] 측정 위치도(측정 장소)

덕수학교 교사동 석면해체제거공사



범례	*NO		
	시료채취	부지경계선	해당건물





















[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
6	갱의실	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
7	작업장주변1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
8	작업장주변2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
9	음압기배출구1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
10	음압기배출구2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
11	음압기배출구3	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
12	음압기배출구4	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
13	음압기배출구5	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
14	음압기배출구6	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
15	음압기배출구7	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
16	음압기배출구8	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
17	음압기배출구9	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
18	음압기배출구10	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
19	음압기배출구11	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
20	폐기물반출구1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
21	폐기물반출구2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-

22	폐기물반출구3	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/30	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

**[별 첨3] 측정 사진**


측정 지점	시작 사진 / 시간	종료 사진 /시간	시작 사진 / 시간	종료 사진 / 시간
부지경계선1,2	 8:00	 12:00	 8:05	 12:05
부지경계선3,4	 8:10	 12:10	 8:15	 12:15
위생설비입구/ 괘의실	 8:20	 9:00	 8:25	 9:05
작업장주변1,2	 8:45	 10:45	 11:00	 13:00
음압기배출구1,2	 9:00	 9:40	 9:05	 9:45
음압기배출구3,4	 11:10	 11:50	 11:12	 11:52

측정 지점	시작 사진 / 시간	종료 사진 / 시간	시작 사진 / 시간	종료 사진 / 시간
음압기배출구5,6	 11:15	 11:55	 13:10	 13:50
음압기배출구7,8	 13:12	 13:52	 13:15	 13:55
음압기배출구9,10	 14:10	 14:50	 14:12	 14:52
음압기배출구11 /폐기물반출구1	 14:15	 14:55	 8:30	 9:10
폐기물반출구2,3	 8:35	 9:15	 14:40	 15:20

[별첨1] 측정 위치도(측정 장소)

덕수학교 교사동 석면해체제거공사



범례	*NO		
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
6	작업장주변	지역시료채취펌프 (SARA-5100)		10.00	20/07/31	불검출 [검출한계 0.002미만]	
7	음압기배출구1	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
8	음압기배출구2	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
9	음압기배출구3	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
10	음압기배출구4	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
11	음압기배출구5	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
12	음압기배출구6	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
13	음압기배출구7	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
14	음압기배출구8	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
15	음압기배출구9	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
16	폐기물반출구	지역시료채취펌프 (SARA-5100)	1	10.00	20/07/31	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진

측정 지점	시작 사진 / 시간	종료 사진 / 시간	시작 사진 / 시간	종료 사진 / 시간
부지경계선1,2	 9:00	 13:00	 9:05	 13:05
부지경계선3,4	 9:10	 13:10	 9:15	 13:15
위생설비입구/ 작업장주변	 9:20	 10:00	 9:30	 11:30
음압기배출구1,2	 9:40	 10:20	 9:42	 10:22
음압기배출구3,4	 9:45	 10:25	 10:07	 10:47
음압기배출구5,6	 10:10	 10:50	 10:12	 10:52



측정 지점	시작 사진 / 시간	종료 사진 / 시간	시작 사진 / 시간	종료 사진 / 시간
음압기배출구7,8	 10:35	 11:15	 10:37	 11:17
음압기배출구9 /폐기물반출구	 10:40	 11:20	 9:25	 10:05







[별첨1] 측정 위치도(측정 장소)

덕수학교 교사동 석면해체제거공사



번 례	*NO		
	시료채취	부지경계선	해당건물

**[별첨3] 측정 사진**

측정 지점	시작 사진 / 시간	종료 사진 /시간	시작 사진 / 시간	종료 사진 / 시간
폐기물보관지점 1,2	 8:00	 08:40	 8:00	 08:40
폐기물보관지점 3	 08:02	 08:42	