

[별첨1] 측정 위치도(측정 장소)

신전면사무소 천정 석면 교체사업	측정일시	22.06.04.	
<p>편 례</p>	<p>*NO 시료채취</p>	<p> 부지경계선</p>	<p> 해당건물</p>

[별첨2] 측정 결과 (측정일시 22.06.04.)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	9.90	22/06/04	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	9.69	22/06/04	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	9.82	22/06/04	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	9.75	22/06/04	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	9.54	22/06/04	불검출 [검출한계 0.002미만]	-
6	작업장주변	지역시료채취펌프 (SARA-5100)	1	9.72	22/06/04	불검출 [검출한계 0.002미만]	-
7	음압기배출구1 (2층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.84	22/06/04	불검출 [검출한계 0.002미만]	-
8	음압기배출구2 (2층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.79	22/06/04	불검출 [검출한계 0.002미만]	-
9	음압기배출구3 (2층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.98	22/06/04	불검출 [검출한계 0.002미만]	-
10	음압기배출구4 (2층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.93	22/06/04	불검출 [검출한계 0.002미만]	-
11	갱의실& 폐기물반출구 (2층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.52	22/06/04	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진 (측정일시 22.06.04.)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2	 9:00	 13:10	 9:05	 13:15
부지경계선 3,4	 9:10	 13:20	 9:15	 13:25
위생설비입구 / 작업장주변	 9:20	 10:05	 9:23	 11:33
음압기배출구 1,2 (2층 1구역)	 9:28	 10:13	 9:30	 10:15
음압기배출구 3,4 (2층 1구역)	 9:30	 10:15	 9:32	 10:17
갱의실& 폐기물반출구 (2층 1구역)	 15:30	 16:15	 -	 -

[별첨1] 측정 위치도(측정 장소)

















신전면사무소 천정 석면 교체사업		측정일시	22.06.05.
범례	*NO		
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과 (측정일시 22.06.05.)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	9.97	22/06/05	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	9.73	22/06/05	불검출 [검출한계 0.002미만]	-
3	작업장주변	지역시료채취펌프 (SARA-5100)	1	9.89	22/06/05	불검출 [검출한계 0.002미만]	-
4	음압기배출구1 (2층 2구역)	지역시료채취펌프 (SARA-5100)	1	9.65	22/06/05	불검출 [검출한계 0.002미만]	-
5	음압기배출구2 (2층 2구역)	지역시료채취펌프 (SARA-5100)	1	9.86	22/06/05	불검출 [검출한계 0.002미만]	-
6	음압기배출구3 (1층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.78	22/06/05	불검출 [검출한계 0.002미만]	-
7	갱의실& 폐기물반출구1 (2층 2구역)	지역시료채취펌프 (SARA-5100)	1	9.57	22/06/05	불검출 [검출한계 0.002미만]	-
8	갱의실& 폐기물반출구2 (1층 1구역)	지역시료채취펌프 (SARA-5100)	1	9.86	22/06/05	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

- 금일 우천으로 부지경계선3, 부지경계선4, 위생설비입구 측정을 생략함.

[별첨3] 측정 사진 (측정일시 22.06.05.)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2	 7:30	 11:40	 7:35	 11:45
작업장주변 / 음압기배출구1 (2층 2구역)	 9:00	 11:10	 7:40	 8:25
음압기배출구2 (2층 2구역) / 음압기배출구3 (1층 1구역)	 7:41	 8:26	 11:50	 12:35
갱의실& 폐기물반출구1 (2층 2구역)/ 갱의실& 폐기물반출구3 (1층 1구역)	 11:00	 11:45	 14:00	 14:45













[별첨1] 측정 위치도(측정 장소)

신전면사무소 천정 석면 교체사업		측정일시	22.06.06.
범례	*NO	[Red Box]	[Blue Box]
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과 (측정일시 22.06.06.)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	폐기물보관지점1	지역시료채취펌프 (SARA-5100)	1	9.86	22/06/06	불검출 [검출한계 0.002미만]	-
2	폐기물보관지점2	지역시료채취펌프 (SARA-5100)	1	9.86	22/06/06	불검출 [검출한계 0.002미만]	-
3	폐기물보관지점3	지역시료채취펌프 (SARA-5100)	1	9.69	22/06/06	불검출 [검출한계 0.002미만]	-
4	폐기물보관지점4	지역시료채취펌프 (SARA-5100)	1	9.68	22/06/06	불검출 [검출한계 0.002미만]	-
5	폐기물보관지점5	지역시료채취펌프 (SARA-5100)	1	9.81	22/06/06	불검출 [검출한계 0.002미만]	-
6	폐기물보관지점6	지역시료채취펌프 (SARA-5100)	1	9.84	22/06/06	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진 (측정일시 22.06.06.)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	11:30	12:15	11:30	12:15
폐기물보관지점 3,4				
	11:31	12:16	11:32	12:17
폐기물보관지점 5,6				
	11:32	12:17	11:34	12:19

[별첨1] 측정 위치도(측정 장소)

신전면사무소 천정 석면 교체사업	측정일시	22.06.07.	
<p>비 례</p>	<p>*NO 시료채취</p>	<p> 부지경계선</p>	<p> 해당건물</p>

[별첨2] 측정 결과 (측정일시 22.06.07.)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	폐기물보관지점1	지역시료채취펌프 (SARA-5100)	1	9.71	22/06/07	불검출 [검출한계 0.002미만]	-
2	폐기물보관지점2	지역시료채취펌프 (SARA-5100)	1	9.87	22/06/07	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진 (측정일시 22.06.07.)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	8:00	8:45	8:02	8:47

[별첨1] 측정 위치도(측정 장소)

신전면사무소 천정 석면 교체사업	측정일시	22.06.08.	
			
편 례	*NO		
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과 (측정일시 22.06.08.)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	폐기물보관지점1	지역시료채취펌프 (SARA-5100)	1	9.91	22/06/08	불검출 [검출한계 0.002미만]	-
2	폐기물보관지점2	지역시료채취펌프 (SARA-5100)	1	9.98	22/06/08	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진 (측정일시 22.06.08.)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2	 <p data-bbox="422 622 480 656">8:10</p>	 <p data-bbox="710 622 767 656">8:55</p>	 <p data-bbox="997 622 1054 656">8:10</p>	 <p data-bbox="1284 622 1342 656">8:55</p>